

RS80faq.txt

You can solder 22K resistors across the 75K resistors R4 and R14 and that should bring it down to what you want.

Or call and get an RA and we will make the mod free of charge.

The schematic for 07 and earlier is at www.rolls.com/pdf/rs80sch8087.pdf